BUILDING AND GROUNDS BUILDING SUMMARY AND LONG RANGE NEEDS

HIGH SCHOOL

Roofs:

Between 2011-2016 layover roofs were applied to 95% of building, projected

lifespan is 15-20 years.

Flooring:

2013-2016 carpet replacement in building offices completed-life cycle 10-12

Ceilings:

2016 hallway ceiling replacement, science room and café

Lighting:

2008-2016 all lighting fixtures upgraded to T-8 with electronic ballasts

Heating:

2016 gym upgrade

Electrical:

2016 service upgrade

Fire Alarm System: updated in about 2008

Entryways:

2010-2016 replaced all main exterior doors, ADA compliant

Long Range needs:

Roofs:

2026 will begin another replacement cycle

Flooring:

library (2017) and band room, no other flooring needs classroom ceiling tile replacement in next 10 years

Ceilings: Lighting:

none, LED at some point when grant funding available

Windows:

in the next 10 years

Heating:

café boiler within 2 years, 4 others good for another 15 years

Electrical:

Entryways:

2017 receiving door replacement, minimal

MIDDLE SCHOOL

Roofs:

Between 2008-2016 layover roofs were applied to 95% of building, projected

lifespan is 15-20 years.

Flooring:

2013-2016 carpet replacement in building offices completed-life cycle 10-12

years, tile replacement in computer lab 2013

Ceilings:

2017 hallway ceiling replacement

Lighting:

2008-2016 all lighting fixtures upgraded to T-8 with electronic ballasts

Heating:

none recent Electrical: none recent

Fire Alarm System: updated in early 2000

Entryways:

2010-2016 replaced all main exterior doors, ADA compliant

Long Range needs:

Roofs:

2023 will begin another replacement cycle

Flooring:

library and band room, no other flooring needs

Ceilings:

classroom ceiling tile replacement in next 10 years

Lighting:

none, LED at some point when grant funding available

Windows:

in 20 years

Heating:

5/6 boiler within 2 years, the other boiler good for another 15 years

Electrical: none Entryways: minimal

ELEMENTARY SCHOOL

Roofs: Between 2008-2017 layover roofs were applied to 100% of building, projected

lifespan is 15-20 years.

Flooring: 2012-2014 entryway tile replacement, carpet replacement in music room

Ceiling: 2014 hallway ceiling replacement

Lighting: 2008-2016 all lighting fixtures upgraded to T-8 with electronic ballasts

Windows: updated in two phases 1995 and 2013

Heating: replaced one in early 2000's

Electrical: Added lines to library and computer labs previous to 2000

Fire Alarm System: updated in 97/98

Entryways: 2010-2016 replaced all main exterior doors, ADA compliant

Long Range needs:

Roofs: 2023 will begin another replacement cycle

Flooring: 1 classroom with carpet in 2017 (return to tile), no other flooring needs, carpet in

office and HI office, 3 classrooms

Ceiling: classroom ceiling tile replacement in next 10 years

Lighting: none, LED at some point when grant funding available

Windows: none, last building lifespan

Heating: none, last building lifespan, Classroom Univent heater replacement within 5 years

Electrical: none unless expansion of use

Entryways: minimal

WELDING SHOP

Roof: replaced in 2005, no additional needs

Flooring: none
Ceiling: none
Lighting: upgraded
Windows: no needs

Heating: replacement in 5-10 years

Electrical: none

Upgrades: welding booth exhaust, need an upgrade to other system within two years

WOOD SHOP

Roof: replaced in 2008-2014, no additional needs

Flooring: none Ceiling: none Lighting: upgraded

Windows: replaced in 2014

Heating: boiler replaced in 2015

Electrical: none Upgrades: none

HEMELGARN FIELD

Upgrades:

All-weather track

Fencing

Bleacher footboards, risers, railing, stairs, (seating update within 10 yrs.)

Bleachers made handicap accessible

New press box

Expanded pole barn and updated

Concession stand paint/upkeep (will need shingles in 5 years)

ATHLETICS

Upgrades:

fencing replacement (will need to continue over next 5 years)

Field upgrades to varsity baseball and varsity softball, JV as well

Dugouts added to fields

GROUNDS

Upgrades:

District Asphalt and Sealing 100% Complete (need sealing every year,

replacement to begin another cycle within 5 years)

Walkways: concrete replaced as needed (continue on an as needed basis)

Building access walkways meet ADA compliance

Fencing (will need to continue replacement over next 5 years)
Painting (continue cycle for exterior grounds using current staff)

Painting (begin interior of buildings using current staff)