4

28

29

Ida Public Schools Capitol Improvement Planning Community Selected Scope of Work 5/12/21 (V9)



11 Yellow Highlight Indicates Essential Items

Selected Items

High School

14	<u>Description</u>	Budgeted Cost	<u>Category</u>
15	Reconstruct Exterior Walls at Classroom Wing Additions	\$ 849,772	Safety
16	Replace Existing Floor Tile in Classrooms	\$ 353,140	Safety
17	Replace Exterior Windows with New Insulated Windows	\$ 2,132,353	Improvements
18	Create Secure Entry @ West Entrance	\$ 141,088	Safety
19	Update 30 Classrooms - Ceilings, Paint, Millwork, Added Storage	\$ 1,554,919	improvements
	Option A - Remodel Existing Biology/Chemistry Room into Standard		
20	Classroom (Rms 114 & 116)	\$ 889,682	Safety/Improvements
21	Option A - Physics Improvements Rm 303 & 305 (Door and Gas)	\$ 28,010	Safety/Improvements
	Replace Classroom Unit Ventilators (30) (Prepared for Future		
22	Cooling)	\$ 1,116,956	Improvements
23	Replace Pneumatic Control System with New DDC Control System	\$ 326,161	Improvements
24	Replace Interior Lighting with LED Fixtures and Controls	\$ 2,076,264	Improvements
25	Option A - Addition for Visiting Girl's Locker Room	\$ 711,527	Improvements
26	Replace Corridor Doors	\$ 350,306	Safety
27	Subtotal High School	\$ 10,530,177	

Selected Items Middle School

Description **Budgeted Cost** Category Reconstruct Exterior Walls at 5th & 6th Grade Wing and 7th & 8th 32 Grade Wing To Resolve Drainage Issue 1,579,269 Improvements Support Interior Masonry Classroom Walls at 7th & 8th Grade 536,497 Improvements 34 Replace Existing Asbestos Containing Floor Tile in Classrooms \$ 977,437 Improvements 35 Create Secure Entry \$ 148,513 Safety Update Classrooms - Ceilings, Paint, Millwork, Added Storage (26 1,376,031 Improvements 37 Science Lab Classroom Improvements (6th, 7th and 8th Grades) \$ 493,992 Curriculum 38 Replace Existing Boiler with New Condensing Boiler (1) \$ 355,831 Improvements Replace Classroom Unit Ventilators (26) (Prepared for Future 968,028 Improvements Replace Existing Heating and Ventilation Control System with New 40 DDC Control System 326,161 Improvements 41 Replace Interior Lighting with LED Fixtures and Controls \$ 1,476,254 Improvements 42 Replace Existing Classroom Doors ADA Hardware 152,040 Safety 43 **Subtotal Middle School** 8,390,054

	В		E	F		
44						
	Selected Iter	n	2			
45	Elementary Sc	nc	001			
47	<u>Description</u>		Budgeted Cost	<u>Category</u>		
48	Replace floor tile in classrooms	\$	310,048	Improvements		
	Update Classrooms - Ceilings, Paint, Millwork, Add Storage (29 CR's)					
_	(Excludes PK CR's)	\$, ,	Improvements		
_	Option A - Classroom Addition (7 CR's including Art and Music)	\$		Curriculum		
	Option A - Multi-purpose Room/Gymnasium & Restroom Addition	\$ \$		Curriculum		
52	Replace Boiler (1) Replace Classroom unit ventilators (36) (Prepared for Future	Ş	293,587	Improvements		
53	Cooling)	\$	1 3/10 3/17	Improvements		
	Replace lighting with new LED Lights and Controls	\$		Improvements		
J-	Replace lighting with new 225 Eights and controls	7	1,400,273	Improvements		
55	Replace Sections of Cracked Concrete Floors	\$	408,442	Improvements		
	·		•	·		
56	Replace Doors and Hardware	\$	540,959	Safety		
57	Replace Heating Pipe Under Concrete Floor	\$	183,206	Improvements		
58	Replace Ceilings (30%)	\$	190,608	Improvements		
	Option A - Remodel 2 Classrooms into a New Office & Addition for					
59	Secure Vestibule (Consider # 30 above to replace the 2 CR's)	\$	835,387	Safety		
	Option A - Enlarge/Remodel 3 Individual Restrooms in Hearing	_				
	Impaired Wing	\$		Ilmnrovements		
	, ,		186,734			
61	Replace Pneumatic controls with DDC	\$	326,161	Improvements		
61 62	, ,	\$				
61	Replace Pneumatic controls with DDC Subtotal Elementary School	\$	326,161 18,736,215			
61 62	Replace Pneumatic controls with DDC	\$	326,161 18,736,215			
61 62 63	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter	\$ \$	326,161 18,736,215			
61 62	Replace Pneumatic controls with DDC Subtotal Elementary School	\$ \$	326,161 18,736,215			
61 62 63	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter	\$ \$	326,161 18,736,215			
61 62 63	Subtotal Elementary School Selected Iter Welding Shop Bu	\$ \$	326,161 18,736,215 S ding	Improvements		
61 62 63 64	Subtotal Elementary School Selected Iter Welding Shop Bu	\$ ns	326,161 18,736,215 S ding	Improvements Category		
61 62 63 64 66 67	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter Welding Shop Bu Description Option A - Update Lighting to LED	s s uil	326,161 18,736,215 Siding Budgeted Cost 111,924	Category Improvements		
61 62 63 64 66 67 68	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter Welding Shop Bu Description Option A - Update Lighting to LED Increase Building Ventilation	s s uil	326,161 18,736,215 ding Budgeted Cost 111,924 46,185	Category Improvements Safety		
61 62 63 64 66 67 68 69	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter Welding Shop Bu Description Option A - Update Lighting to LED Increase Building Ventilation Upgrade Electrical Service	s s uil	326,161 18,736,215 ding Budgeted Cost 111,924 46,185 30,525	Category Improvements Safety Improvements		
61 62 63 64 66 67 68 69	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter Welding Shop Bu Description Option A - Update Lighting to LED Increase Building Ventilation Upgrade Electrical Service Replace Fans	s s uil	326,161 18,736,215 Siding Budgeted Cost 111,924 46,185 30,525 52,078	Category Improvements Safety		
61 62 63 64 66 67 68 69 70	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter Welding Shop Bu Description Option A - Update Lighting to LED Increase Building Ventilation Upgrade Electrical Service	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$	326,161 18,736,215 ding Budgeted Cost 111,924 46,185 30,525	Category Improvements Safety Improvements Improvements		
61 62 63 64 66 67 68 69 70 71	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter Welding Shop Bu Description Option A - Update Lighting to LED Increase Building Ventilation Upgrade Electrical Service Replace Fans Provide New Welding Booths (4)	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$	326,161 18,736,215 Siding Budgeted Cost 111,924 46,185 30,525 52,078 150,424	Category Improvements Safety Improvements Improvements		
61 62 63 64 66 67 68 69 70 71 72	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter Welding Shop Bu Description Option A - Update Lighting to LED Increase Building Ventilation Upgrade Electrical Service Replace Fans Provide New Welding Booths (4) Subtotal Welding	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$	326,161 18,736,215 Siding Budgeted Cost 111,924 46,185 30,525 52,078 150,424 391,136	Category Improvements Safety Improvements Improvements		
61 62 63 64 66 67 68 69 70 71 72	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter Welding Shop Bu Description Option A - Update Lighting to LED Increase Building Ventilation Upgrade Electrical Service Replace Fans Provide New Welding Booths (4) Subtotal Welding Selected Iter	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$	326,161 18,736,215 Siding Budgeted Cost 111,924 46,185 30,525 52,078 150,424 391,136	Category Improvements Safety Improvements Improvements		
61 62 63 64 66 67 68 69 70 71 72 73	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter Welding Shop Bu Description Option A - Update Lighting to LED Increase Building Ventilation Upgrade Electrical Service Replace Fans Provide New Welding Booths (4) Subtotal Welding Selected Iter Site	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$	326,161 18,736,215 Siding Budgeted Cost 111,924 46,185 30,525 52,078 150,424 391,136	Category Improvements Safety Improvements Improvements		
61 62 63 64 66 67 68 69 70 71 72	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter Welding Shop Bu Description Option A - Update Lighting to LED Increase Building Ventilation Upgrade Electrical Service Replace Fans Provide New Welding Booths (4) Subtotal Welding Selected Iter Site	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$	326,161 18,736,215 Siding Budgeted Cost 111,924 46,185 30,525 52,078 150,424 391,136	Category Improvements Safety Improvements Improvements		
61 62 63 64 66 67 68 69 70 71 72 73	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter Welding Shop Bu Description Option A - Update Lighting to LED Increase Building Ventilation Upgrade Electrical Service Replace Fans Provide New Welding Booths (4) Subtotal Welding Selected Iter Site	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$	326,161 18,736,215 Siding Budgeted Cost 111,924 46,185 30,525 52,078 150,424 391,136	Category Improvements Safety Improvements Improvements		
61 62 63 64 66 67 68 69 70 71 72 73	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter Welding Shop Bu Description Option A - Update Lighting to LED Increase Building Ventilation Upgrade Electrical Service Replace Fans Provide New Welding Booths (4) Subtotal Welding Selected Iter Site	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$	326,161 18,736,215 Significant of the second of the secon	Category Improvements Safety Improvements Improvements Curriculum		
61 62 63 64 66 67 68 69 70 71 72 73	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter Welding Shop Bu Description Option A - Update Lighting to LED Increase Building Ventilation Upgrade Electrical Service Replace Fans Provide New Welding Booths (4) Subtotal Welding Selected Iter Site	s s iii	326,161 18,736,215 ding Budgeted Cost 111,924 46,185 30,525 52,078 150,424 391,136	Category Improvements Safety Improvements Improvements Curriculum Category		
61 62 63 64 66 67 68 69 70 71 72 73 74	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter Welding Shop Bu Description Option A - Update Lighting to LED Increase Building Ventilation Upgrade Electrical Service Replace Fans Provide New Welding Booths (4) Subtotal Welding Selected Iter Site Description Option A - New Preschool Playground	s s iii s s s s s	326,161 18,736,215 ding Budgeted Cost 111,924 46,185 30,525 52,078 150,424 391,136 Budgeted Cost 464,104	Category Improvements Safety Improvements Improvements Curriculum Category Curriculum		
61 62 63 64 66 67 68 69 70 71 72 73	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter Welding Shop Bu Description Option A - Update Lighting to LED Increase Building Ventilation Upgrade Electrical Service Replace Fans Provide New Welding Booths (4) Subtotal Welding Selected Iter Site Description Option A - New Preschool Playground Option A - New Elementary School Playground	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	326,161 18,736,215 ding Budgeted Cost 111,924 46,185 30,525 52,078 150,424 391,136 Budgeted Cost 464,104 464,104	Category Improvements Safety Improvements Improvements Curriculum Category		
61 62 63 64 66 67 68 69 70 71 72 73 74 76 77 78	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter Welding Shop Bu Description Option A - Update Lighting to LED Increase Building Ventilation Upgrade Electrical Service Replace Fans Provide New Welding Booths (4) Subtotal Welding Selected Iter Site Description Option A - New Preschool Playground Option A - New Elementary School Playground Subtotal Site	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	326,161 18,736,215 ding Budgeted Cost 111,924 46,185 30,525 52,078 150,424 391,136 Budgeted Cost 464,104	Category Improvements Safety Improvements Improvements Curriculum Category Curriculum		
61 62 63 64 66 67 68 69 70 71 72 73 74 76 77 78	Replace Pneumatic controls with DDC Subtotal Elementary School Selected Iter Welding Shop Bu Description Option A - Update Lighting to LED Increase Building Ventilation Upgrade Electrical Service Replace Fans Provide New Welding Booths (4) Subtotal Welding Selected Iter Site Description Option A - New Preschool Playground Option A - New Elementary School Playground	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	326,161 18,736,215 ding Budgeted Cost 111,924 46,185 30,525 52,078 150,424 391,136 Budgeted Cost 464,104 464,104	Category Improvements Safety Improvements Improvements Curriculum Category Curriculum		